

# PRODUCT CHANGE NOTICE

Notification Date: 12th August 2011 PCN # FFC2A30-002

**Drawing Revision Letter:** C

# **Product Identification**

1.Mylar Tape issue:

FFC2A30-04-x-x to FFC2A30-46-x-x

All circuit sizes

Height Issue:

FFC2A30-35-x-x to FFC2A30-46-x-x

35 to 46 circuit versions only, other smaller circuit sizes remain unaffected.

### Effective from date code/batch code

Immediately.

Batch Code From: 20110812

### **Description of Change**

1. Mylar Tape:

Products have previously been supplied without mylar tape, all future shipments will include mylar tape.

2. Dimension E, total height of connector with actuator closed, changes from 4.9mm to 4.4mm for 35 - 46 circuits.



## Reason for Change

- 1. Correct missing Mylar tape error.
- 2. Tooling rationalisation, focus on 4.4mm height insulator tool to produce all circuit sizes.

# Anticipated impact on form, fit, function or reliability

- 1. If customer is using product in automatic pick and place function mylar tape is required.
- 2. Height change -lower height. Customer's must check their design.

### Required inventory action

Run out existing stock or exchange for new version, customer discretion.

## **Contact Information**

Question, comments or suggestions? Please contact GCT.

Global Connector Technology HK Limited Unit 1204, 12/F, Fortress Tower, 250 Kings Road, North Point, Hong Kong

> Tel: +852 2578 9030 Fax: +852 2578 9000 E-mail: sales@qct-apac.com

Global Connector Technology, Inc 3 Industrial Park Road, Medway, MA 02053 USA

Tel: +1 508-570-2438 Fax: +1 508-796-6162 E-mail: sales@gct-americas.com Global Connector Technology UK Limited 7 Sutherland Court, Brownfields, Welwyn Garden City, Hertfordshire, AL7 1BJ, United Kingdom

> Tel: +44 (0)1707 321122 Fax: +44 (0)1707 321121 E-mail: sales@gct-europe.com